

WMC - Fire Door Summary

Building	Fire Door Total Count	Fire Doors that PASS	Fire Doors with Deficiencies	Work Orders Issued to Repair Shop	Fire Labels Needed	Vendor Repairs Needed		
						High Priority (1)	Medium Priority (2)	Low Priority (3)
ACP	172	62	110	25	14	0	4	93
BHC	40	0	40	22	30	0	8	21
Macy	18	1	17	10	8	0	6	6
Main	346	73	273	117	123	37	62	99
MFCH	91	14	77	35	34	2	3	55
TCC	40	7	33	22	8	1	11	15
Totals	707	157	550	231	217	40	94	289

Key:

High Priority (1) = Door not positive latching, Latching hardware not installed / missing, Door (s) delaminating, Frame damaged, Door (s) damaged

Medium Priority (2) = Hardware not installed / missing, Bottom rod not installed/missing, Door (s) delaminating, Glass / glazing not fire rated, Door (s) damaged, Door not self-closing

Low Priority (3) = Hole (s) in frame/door, Continuous hinge not fire rated, Clearances/Undercuts exceed max allowable, Protection plate >16" not labeled, Exit hardware not fire rated